



Time this mark-
At 33 1/3 RPM it takes
180 sec for 100 revolutions.
Use $(1 - (\text{actual}/\text{target})) * 100$
for percentage error.

33 1/3 RPM - 60 HZ - 216 BARS
45 RPM - 60 HZ - 160 BARS